strength was measured in comparison with a control non-corroded bar. Figures 3.35, 3.36, and 3.37 show the various steps in the tension test.



Figures 3.35 – Tension Test Setup



Figure 3.36 – Extensometer Setup